


MR.CARVE

M4 PRO-APP Operations Manual

Please carefully read this Operations Manual before use and keep it properly.



Model: M4 PRO-APP

Contents

Safety Precautions	03
Product structure accessories	04
Product parameters	06
Assembly steps	07
180°rotation instructions	08
focus	09
Software acquisition and installation	10
Software Description	11
Introduction to common functions	12
• Draw graphics	12
• Draw text	13
• text filling	14
• Import pictures	15
• Image processing	16
• Import vector graphics	18
• Rotate text marking	19
• Marking control	21
Material parameters	22
common problem	24

Mobile APP download	26
Mobile APP connection	27
Software Description	29
Draw text	30
text filling	32
Image processing	33
Import vector graphics	35
Rotating text Mark	36
Ring Mark	37
focus	39
Start marking	40

Safety Precautions

In order to prevent damage to your personal and property safety and to use this product safely and correctly, please read the user manual carefully and follow the steps in the user manual.

Safety Precautions

- ★ Before operating the equipment, users must carefully read the user manual and strictly abide by the operating procedures.
- ★ Laser processing may be risky, and users should carefully consider whether the object to be processed is suitable for laser operations.
- ★ Processing objects and emissions should comply with local laws and regulations.

*This equipment uses a Class IV laser (intense laser radiation). This laser radiation may cause the following conditions:

- ① Ignite surrounding flammable materials;
 - ② During laser processing, other radiation and toxic and harmful gases may be produced depending on the processing objects;
 - ③ Direct exposure to laser radiation can cause human injury. The place of use must be equipped with fire-fighting equipment. It is prohibited to stack flammable and explosive items around the workbench and equipment. At the same time, good ventilation must be maintained.
- *The environment where the equipment is located should be dry, free of pollution, vibration, strong electricity, strong magnetism and other interference and influence. Working environment temperature 10-40°C, working environment humidity 5-95% (no condensation)

★ Equipment working voltage: AC100-240V.

*The engraving machine and other related equipment must be safely grounded before it can be powered on.





★ When the equipment is powered on, it needs to be on duty at all times. All power supplies must be cut off before personnel leave to prevent abnormal conditions from occurring. If any abnormality occurs, please cut off the power immediately!

*It is strictly prohibited to place any irrelevant total reflection or diffuse reflection objects in the device to prevent the laser from being reflected on the human body or flammable objects.

*The equipment should be kept away from electrical equipment that is sensitive to electromagnetic interference and may cause electromagnetic interference to it.

*There are high voltages or other potential dangers inside the laser equipment, and non-professionals are strictly prohibited from dismantling it.

Product structure accessories



Parts List



External antenna



Auxiliary positioning tools



goggles



test card



U disk



Allen wrench



focus paper



data cable



power cable



Product parameters


Detailed Parameters of Machine M4	
Laser power	Blue Light: 5W / Red Light: 2W
ambient temperature	-10°C~45°C
Repeat accuracy	≤0.001mm
Marking depth	0.015-0.2mm
Marking accuracy	≤0.001mm
Marking speed	≤10000mm/s
cooling method	Built-in fan
Laser wavelength	Blue Light: 455nm / Red Light: 1064nm
Marking format	70*70mm
Marking line width	0.001-0.05mm
Machine net weight	6.26kg
Machine size	300mm* 200mm* 320mm (L*W*H)

Assembly steps



01

1. Place the machine on a flat surface



02

2. Move the Y-axis upward and snap it into the base



03

3. Tighten the screws to fix the Y-axis



04

4. Place the lens on the right angle plate of the Y-axis and aim it at the four screw holes in the rear



05



5. Tighten the screws to fix the X-axis



06

6. The installation is complete

180°rotation instructions



Loosen the fastening screws and tighten the screws after rotating the X axis of the engraving machine by 180 degrees. Note: After rotating by 180 degrees, the laser head must keep an effective distance of 120mm from the engraving surface when carving the table top or other high objects, otherwise it cannot be focused.


Focus

1.Click "Focus" in the software, and "Focusing..." will appear. At this time, two red light spots will appear on the machine.



2.Insert the test card, lightly press the "Down" and "Up" buttons to adjust, and the two red lights will converge into a red dot to complete the focus.

3.The standard distance between the laser head and the engraving object is 120mm, which is subject to actual measurement.



Software acquisition and installation


method one:

1. Install the driver files in the USB flash drive "Drive\CypressDriverInstaller.exe"

2. Move the folder in the USB flash drive "[Engraving software](#)" Copy it to your computer desktop, open the folder, and double-click "[MR CARVE.exe](#)", Start the software;

Method Two:


If the supplied USB flash drive is accidentally lost, or the software is accidentally deleted. You can visit the official website "<http://www.mrcarve.cn/download>" Obtain and install steps are the same as method 1.




Software opening status page

Software Description

When the mouse stays on a function icon, the usage instructions corresponding to the icon will be displayed.




Draw graphics



- ① Drawing Bar: Draw lines, curves, rectangles, circles, polygons
- ② content display box
- ③ Node editing bar: Edit nodes on the drawn graphics

Draw text






1. Click **T** "TEXT" will appear by default, enter the relevant text in the text input box, and click **Apply** to complete text input.

H Text filling needs to be filled before it can be applied to the engraving;

F Text tool, set alignment, character spacing, arc text, angle and other parameters.

Text filling




1. Click pen the fill settings window;

2. There is no need to set other parameters for text marking. You only need to modify the "Line". The default parameter is 0.03;

Note: Line spacing is the text fill density. The larger the value, the faster the marking speed and the lighter the engraving color; conversely, the smaller the value, the slower the marking speed and the darker the engraving color;


The best effect is achieved when marking on primary metal, spray paint, oxidized paint, electroplated metal, plastic, leather, and other painted materials.

Import pictures



1.Click Open image file

Picture Processing (Portrait/Colored Photo)



1. Adjust the image to the appropriate size;

* In the left window, check "Reverse", "Grayscale", "Fixed DPI" (fill in the parameters 500 for XY respectively), and "Outlets";


* In the left window, check "Two-Way Scanning" and fill in 0.4 in "Dotting Time". Click **Apply** parameters.

2. Marking parameter settings, "Speed (mm/s)" is set to 500, "Power (%)" is set to 100;

Note: People photos/color photos are best engraved on spray painted metal/oxidized painted electroplated metal.

The higher the DPI value, the clearer the engraving effect; the longer the dotting time, the deeper the engraving effect.

Picture Processing (Ordinary Bitmap)



1. Adjust the image to the appropriate size;


*.In the left window, check "Grayscale", "Fixed DPI" (fill in the parameters 500 for XY respectively), and "Outlets";

*.In the left window, check "Two-Way Scanning" and fill in 0.4 in "Dotting Time". Click **Apply** parameters.

4. Marking parameter settings, "Speed (mm/s)" is set to 500, "Power (%)" is set to 100;

Description: The best effect is achieved when engraving on primary metal, spray paint, oxidized paint, electroplated metal, plastic, leather, and other painted materials.

Import vector graphics




- 1.Click import vector files; support PLT, DWG, AI and other formats;
- 2.The imported vector file needs to be filled to complete the marking.
- 3.For vector file filling, there is no need to set other parameters. You only need to modify the "line spacing". The default parameter is 0.03;

Note: The line spacing is the filling density. The larger the value, the faster the marking speed and the lighter the engraving color; conversely, the smaller the value, the slower the marking speed and the darker the engraving color;

The best effect is achieved when marking on primary metal, spray paint, oxidized paint, electroplated metal, plastic, leather, and other painted materials.


Rotating text Mark



The axis of rotation only supports text engraving

- Follow the numbering sequence in the picture above;
- ③ Extended Axis:Y, Enter the diameter of the workpiece to be marked;
- ⑤ Enter value ⑤; Inp ⑥ parameters "6400"
- ⑦ Text content needs to be rotated 90°, shortcut key "ctrl" + Arrow key "←"
- ⑧ Text filling needs to be unchecked" Object Overall Calc"


Ring Mark



The axis of rotation only supports text engraving

- 1 Follow the numbering sequence in the picture above;
- 2 **3** Extended Axis:Y, Enter the diameter of the workpiece to be marked;
- 3 **5** Enter value 1; **6** Set parameters "6400"
- 4 **7** Text content needs to be rotated 90°, shortcut key "ctrl" + Arrow key "←"
- 5 **8** Text filling needs to be unchecked "Object Overall Calc"

Mark Control



Focus: The machine will show two red light spots

Red (F1): Preview the current engraving position, red light rectangle preview mode

Mark(F2): Start marking

Continuous Mark: Repeat engraving

Select Mark: Multiple objects, select one to engrave

Recommended parameter adjustment:
Speed(mm/s):500
Power(%):100
Frequency(KHZ):30

Switch between blue and red light (M4 model only)

After checking, set to outline preview mode
(movement axis preview must be checked)

Blue light, References of Carving Parameters for Different Materials

Picture, Text and Vector File			
Material	Line Spacing	Power	Speed
Wood	0.05/ 0.01	100	500/700
Bamboo	0.005 / 0.001	100	500/700
Plastic	0.05	100	1000 / 1500
Leather	0.05	100	1000 / 1500
Stone	0.01	100	500
Glass / Ceramic (Need color paper)	0.05	100	500
Paint Surface Material	0.05/0.01	100	200/400

Red light, References of Carving Parameters for Different Materials

Picture, Text and Vector File			
Material	Line Spacing	Power	Speed
Metal	0.01 or 0.005 or 0.001	100	300 or 500
Paint Surface Metal	0.005 or 0.001	100	500
Plastic	0.05	100	1000 or 1500
Leather	0.05 or 0.01	100	1000 or 1500
Stone	0.01	100	500
Paint Surface Glass	0.05	100	500
Paint Surface Material	0.05	100	1000 or 1500

Black and White Picture (Ordinary Bitmap)

Material	Picture Settings	Power	Speed
Metal	Grayscale (Checked) Fixed DPI (x300 y300) Lattice point (Checked) Two-way scanning (Checked) Dotting time (0.4~0.5ms) Adjustment point power (Checked)	100	200
Paint Surface Metal		100	300
Plastic		100	500
Leather		100	500
Stone		100	200
Paint Surface Material		100	500

Colored Picture (Landscape and Portrait)

Paint Surface Metal	Reversal (Checked) Grayscale (Checked) Fixed DPI (x500 y500) Lattice Point (Checked) Two-way scanning (Checked) Dotting time (0.4~0.5ms) Adjustment point power (Checked)	100	500
Electroplated Metal			
Oxidized Metal			
ABS			

FAQ

I. The machine does not respond when powered on.

1. Power connection failure: check the socket, switch and socket on the machine body to ensure that they have been properly plugged and connected to power; check the Power button on the panel to make sure it is pressed and the button light is on.

II. Unable to connect to the computer

1. Not connected to the USB cable: check the computer and machine interface of the USB cable to ensure that it is properly connected. The USB interface on the front panel of some desktop computers is invalid, so it needs to be connected to the socket at the rear of the host.

2. The driver is not installed properly: install the driver according to the instructions. If the computer identifies the device as a serial port after installation, the hardware connection is OK.

3. Other special cases: disconnect the USB cable and power supply. After the equipment is completely powered off for 5 seconds, connect it to the power again.

III. Light carving or no carving

1. Inaccurate focusing: read the focusing section of the Operations Manual for accurate focusing.

2. Carving speed: a result of too high speed or too short burning time. Read the carving parameters section of the Operations Manual to readjust the parameters.

3. Shallow picture: the imported picture needs to be clear. If the lines are too fine and the color is too light, the carving effect will be affected directly.

4. Placement of object: as the laser focal distance is fixed, the object to be carved needs to be flat, parallel to the machine body. If the object to be carved is tilted, the focal distance is inaccurate, resulting in abnormal carving effect.

1. Mobile App Download

1. Scan the following QR code to download the mobile app



Android




iOS

System Requirements: Android:7.0+, IOS:13.0+

Tips: 1. Android phones need to use the mobile browser to scan the QR code to download;
2. After successful installation, you need to give the corresponding permissions;



MRCARVE



2. Mobile app connection


1. Plug in the External antenna, plug in the power of the machine, and press the power button on the front
2. Connect to WIFI with "ADD" password: 12345678 and stay connected.



connected



not connected



After connecting to the App, please modify the parameters according to the paper parameter sheet

Steps: "Param" → "Galvanometer" The picture below indicates the location
"Param" → "Preview" indicates the location in the figure below

Marking parameters

Marking	Preview	Galvanometer	Axis of rotation
Offset X(mm): 0.000	Offset Y(mm): 0.000	Angle(°): 0.000	
<input type="checkbox"/> XY swap	<input type="checkbox"/> X reverse	<input type="checkbox"/> Y reverse	Area size (mm): 70
X: <input checked="" type="radio"/> 1.041	<input type="radio"/> 1.000	<input type="radio"/> 0.995	Scale: 64.600 >>
Y: <input checked="" type="radio"/> 0.959	<input type="radio"/> 1.000	<input type="radio"/> 1.002	Scale: 64.906 >>

Close Ok

Marking parameters


Marking	Preview	Galvanometer	Axis of rotation
Preview method:	<input type="radio"/> Outline	<input checked="" type="radio"/> Circumscribed rectangle	
Speed of red light (us):	3000		
Offset X(mm):	0.000	Size ratio X:	1.000
Offset Y(mm):	0.000	Size ratio Y:	1.000

Close Ok





The laser needs to select "CO2"


3. Software Description



4. Draw text




- 1 Click on the left to add text
 - 2 Enter text and select font, click "OK" to complete text editing.
 - 3 Workspace size scaling
 - 4 Work area, please do not draw content beyond the area
 - 5 Show work area
 - 6 Drag work area
 - W Width, unit: mm
 - H Height, unit: mm
 - lock ratio
 - A+ Enlarge content
 - A- Content reduced
- Fine-tune the position up, down, left, and right
The distance is in the middle
Unit: mm




Attr→Element Properties, you can edit text content and fonts twice

5.Text Filling




- 1 Click open the filling settings window
Filling
- 2 There is no need to set other parameters for text marking. You only need to modify the "line spacing". The default parameter is 0.03.



illustrate:

Line spacing is text fill density. The larger the value, the faster the marking speed and the lighter the engraving color; conversely, the smaller the value, the slower the marking speed and the darker the engraving color; The best effect is achieved when marking on primary metal, spray paint, oxidized paint, electroplated metal, plastic, leather, and other painted materials.


6.Picture Processing (Portrait/Colored Photo)



illustrate:

People's photos/color photos are best engraved on spray-painted lacquered metal/oxidized lacquered electroplated metal. The higher the DPI value, the clearer the engraving effect; the longer the dotting time, the deeper the engraving effect.


7.Picture Processing (Ordinary Bitmap)



illustrate:

People's photos/color photos are best engraved on spray-painted lacquered metal/oxidized lacquered electroplated metal. The higher the DPI value, the clearer the engraving effect; the longer the dotting time, the deeper the engraving effect.


8.Import vector graphics



illustrate:


People's photos/color photos are best engraved on spray-painted lacquered metal/oxidized lacquered electroplated metal. The higher the DPI value, the clearer the engraving effect; the longer the dotting time, the deeper the engraving effect.

- 1 Click to open the vector file
- 2 Click to open the filling settings window
- 3 There is no need to set other parameters for text marking. You only need to modify the "line spacing". The default parameter is 0.03.



Once the setting is complete, you can focus and mark.
For detailed steps, please refer to the "Focus" and "Start Marking" pages of the manual.

9. RT5 Rotary Axis-Text Marking




- 1 "Setting" → Marking Mode: "Rotary axis marking"
- 2 "Param" → "Axis of rotation", modify the following parameters:
Axis direction: y;
Check RedLight to start point;
Enter diameter value
- 3 Open the "Shaft movement test" window,
Select "Pulse" and fill in a value, such as 16625
Click the left or right arrow
Observe whether the roller drives the object
(such as a cup) to rotate one circle. If it does not
rotate one circle, increase the value of "pulse". If
it exceeds one circle, decrease it until it rotates
exactly one circle.
The "pulse" value of one revolution is the
"number of pulses per revolution"
Finally, fill in the tested pulse value into the
"number of pulses per revolution".


illustrate:

The diameter of the workpiece is different, and the number of pulses per revolution is different. You need to modify the number of pulses per revolution according to the above method. Please contact customer service for a video tutorial.

10.RF2 Rotary Axis-Text Marking




- 1 "Setting" → Marking Mode: "Rotary axis marking"
- 2 "Param" → "Axis of rotation", modify the following parameters:
Axis direction: y;
Check RedLight to start point;
Pulses per revolution: 6400 (RF1 rotation axis only)
Fill in the workpiece diameter according to the actual marked object;



- 1 Click "Text" and enter the engraving content
- 2 Click "Filling" to fill the content solid (only outlines will be carved out without filling)
- 3 Click "Rotate L" and "Rotate R" to make the text vertical as shown in the picture above.

11.Focus and switch Blue/Red light




M4-pro model device, you can switch between "Fiber" and "BlueLight" here

Dual light switching, adaptable to more engraving materials

1.Click "Focus" in the upper right corner of the App, and "Focusing..." will appear. At this time, two red light spots will appear on the machine.

2.Insert the test card, lightly press the "Down" and "Up" buttons to adjust, and the two red lights will converge into a red dot to complete the focus.

3.The standard distance between the laser head and the engraving object is 120mm, which is subject to actual measurement.



12.Start marking





Marking parameters

Marking	Preview	Galvanometer	Axis of rotation
Turn-on delay (us): 300	Light off delay (us): 100		
Power(%): 80	Frequency(khz): 30		
Speed(mm/s): 300 <small>(Invalid marking in image node mode)</small>	Mark method: <input checked="" type="checkbox"/> Select process		
Marking times: 1	<input type="checkbox"/> Save as default		

Close **Ok**

- 1 After drawing "text", "vector graphics", "pictures" and other content, click "Param" in the lower right corner
- 2 In the marking window, enter the power, speed, and fill line spacing. Please refer to the manual "Engraving Parameter Reference for Each Material" (p22)
- 3 Enter the corresponding engraving parameters



- 1 Click "Preview" to display the preview window.
At the same time, the machine displays a preview red light.
Place the carved objects, ready for marking.



- 2 Click "Marking" to complete marking.

MR.CARVE

All contents in this document have been carefully checked. If there are any printing errors or misunderstandings in the content, please consult our company.


Note: If there are any technical improvements to the product, they will be added to the new version of the manual without prior notice.
If there are any changes in the product appearance and color, the actual product shall prevail.

MR.CARVE

M4 PRO-APP使用说明书

使用产品前请仔细阅读本使用说明书，并妥善保管。

型号：M4 PRO-APP



目录

安全注意事项	03
产品结构配件	04
产品参数	06
组装步骤	07
180°旋转使用说明	08
对焦与切换蓝/红光	09
软件获取与安装	10
软件各功能简介	11
常用功能介绍	12
• 绘制图形	12
• 绘制文字	13
• 文本填充	14
• 导入图片	15
• 图片处理	16
• 导入矢量文件	18
• 旋转文本标刻	19
• 标刻控制	21
材质雕刻参数参考	22
常见问题	25

手机APP下载	26
手机APP连接	27
软件各功能简介	29
绘制文字	30
文本填充	32
图片处理	33
导入矢量文件	35
RT5旋转轴文本标刻	36
RT2旋转轴文本标刻	37
对焦与切换蓝/红光	39
开始标刻	40

安全注意事项

为了防止给您的人身及财产安全造成损害，为了您可以安全正确地使用本产品，请仔细阅读使用手册，并按照使用手册的步骤操作。

安全注意事项

★在操作设备之前，用户务必认真阅读使用手册，严格遵守操作规程。

★激光加工可能存在风险，用户应慎重考虑被加工对象是否适合激光作业。

★加工对象及排放物应符合当地的法律、法规要求。

*本设备使用四类激光器（强激光辐射），该激光辐射可能会引起以下情况：

①点燃周边的易燃物；

②激光加工过程中，因加工对象的不同可能会产生其它的辐射及有毒、有害气体；

③激光辐射的直接照射会引起人体伤害，使用场所必须配备消防器材，禁止在工作台及设备周围堆放易燃、易爆物品，同时务必保持通风良好。

*设备所处环境应干燥，无污染、无震动、无强电、强磁等干扰和影响。工作环境温度10-40°C，工作环境湿度5-95%（无凝水）

★设备工作电压：AC100-240V。

*雕刻机及其相关联的其它设备都必须安全接地，方可开机操作。





★设备在开机状态下，需全程值守，人员离开前必须切断所有电源，防止异常状况发生，如有发生请立即断电处理！

*严禁在设备中放置任何不相干的全反射或漫反射物体，以防激光反射到人体或易燃物品上。

*设备应远离对电磁干扰敏感之电气设备，可能对其产生电磁干扰。

*激光设备内部有高压或其它潜在的危险，非专业人员严禁拆卸。

产品结构配件



配件明细

胶棒天线	定位板	护目镜
		
定焦测试片	U盘	六角扳手



产品参数

机器详细参数	
激光功率	蓝光: 5W / 红光: 2W
环境温度	-10°C~45°C
重复精度	≤0.001mm
打标深度	0.015-0.2mm
打标精度	≤0.001mm
打标速度	≤10000mm/s
冷却方式	内置风扇
激光波长	蓝光: 455nm / 红光: 1064nm
打标幅面	70*70mm
打标线宽	0.001-0.03mm
机器净重	6.26kg
机器尺寸	300mm* 200mm* 320mm (L*W*H)

组装步骤



01

1.将机器放置于平面



02

2.将升降轴立起来



03

3.安装螺丝，固定升降轴



04

4.将光路装置放置于升降轴的直角板，对准后四个螺丝孔



05


5.固定光路装置，安装螺丝



06

6.安装完成

180°旋转使用说明



拧松固定螺丝,将雕刻机X轴旋转180°后拧紧螺丝固定。

注意:旋转180°后雕刻桌面或雕刻其它有高度的物品时激光头与雕刻面必须保持120mm有效距离,否则无法聚焦。

对焦与切换蓝/红光


1.放入测试卡片，轻按“Down”及“Up”按键调整，两道红光重合，完成对焦。

2.切换蓝光/红光，在软件里边设置；



3.激光头距离雕刻物的标准：

两道红光汇合一点，即完成对焦。



软件获取与安装


方法一：

1. 安装U盘里的驱动文件“Drive\CypressDriverInstaller.exe”

2. 将U盘里的文件夹“[软件BsIApSimple](#)”复制到电脑桌面，打开该文件夹，双击“[BsIApSimple.exe](#)”，启动软件；

方法二：


如果随机附赠的U盘不慎遗失，或者软件误删除。可通过访问官网“<http://www.mrcarve.cn/download>”获取，安装步骤与方法一相同。



软件打开状态页面


软件各功能简介

鼠标在功能图标上停留，会显示该图标对应的使用说明




- 1 菜单栏
- 2 系统工具栏
- 3 放大工具栏
- 4 对齐工具栏
- 5 辅助工具栏
- 6 绘图工具栏
- 7 对象列表窗
- 8 内容显示框
- 9 标刻参数栏
- 10 对象属性栏
- 11 标刻控制栏
- 12 状态栏

绘制图形



- 1 绘图栏: 绘制直线、曲线、矩形、圆形、多边形
- 2 内容显示框
- 3 节点编辑栏: 对绘制的图形, 进行节点编辑

绘制文字





- 1.点击 **T**，默认出现“TEXT”，在文本输入框内输入相关文字，点击 **应用**，完成文本输入。

H 文本填充，需要填充才能作用到雕刻物上；

F 文本工具，设置对齐方式、字符间距、圆弧文本、角度等参数。

文本填充




1.点击 ，打开填充设置窗口；

2.文字打标不需要设置其他参数，只需要修改“线间距”，默认参数为0.05；

说明：线间距是文字填充密度。数值越大，打标速度越快，雕刻颜色越浅；反之数值越小，则打标速度越慢，雕刻颜色越深；


在原色金属、喷漆烤漆、氧化漆面、电镀金属、塑料、皮革、其它漆面材质上标刻，效果最佳。

导入图片



1.点击 ，弹出“图片属性”窗口，选择自己所需的图片，点击 **打开(O)** 导入图片。

图片处理（人物照片/彩色照片）




1. 调整图片至合适的大小尺寸；
2. 在“图片设置”窗口里，勾选“反转”、“灰度”，“固定 DPI”(XY分别填入参数500)，“网点”；
3. 在“标刻参数”窗口里，勾选“双向扫描”、在“打点时间”填入0.4，点击 **应用** 确定输入参数；

4. 标刻参数设置，“速度(mm/s)”设置为500，“功率(%)”设置为100；

说明：人物照片/彩色照片在喷漆烤漆面金属/氧化漆面电镀金属上雕刻，效果最佳。

DPI数值越高，雕刻效果越清晰，打点时间越大，雕刻效果越深。



图片处理（普通位图）



1. 调整图片至合适的大小尺寸；
2. 在“图片设置”窗口里，勾选“灰度”，“固定 DPI”(XY分别填入参数300)，“网点”；
3. 在“标刻参数”窗口里，勾选“双向扫描”、在“打点时间”填入0.4，点击 **应用** 确定输入参数；
4. 标刻参数设置，“速度(mm/s)"设置为500，“功率(%)”设置为100；

说明：在原色金属、喷漆烤漆、氧化漆面、电镀金属、塑料、皮革、其它漆面材质上雕刻，效果最佳。

导入矢量文件



1.点击 ，导入矢量文件；支持PLT、DWG、AI等格式；

2.导入的矢量文件，需要填充才能完成标刻。




3.矢量文件填充，不需要设置其他参数，只需要修改“线间距”，默认参数为0.05；

说明：线间距是填充密度。数值越大，打标速度越快，雕刻颜色越浅；反之数值越小，则打标速度越慢，雕刻颜色越深；

在原色金属、喷漆烤漆、氧化漆面、电镀金属、塑料、皮革、其它漆面材质上标刻，效果最佳。


旋转文本雕刻



旋转轴只支持文本雕刻

1. 按上图编号顺序操作；
2. ③ 步骤输入需要打标工件的直径；
3. ⑤ 勾选，输入数值5； ⑥ 输入参数 "6400"
4. ⑦ 文本内容需要旋转90°，快捷键" ctrl " + 方向键 " ← "
5. ⑧ 文本填充需要取消勾选" 对象整体计算 "


戒指标刻



旋转轴只支持文本雕刻

1. 按上图编号顺序操作；
2. ③ 步骤输入需要打标工件的直径；
3. ⑤ 勾选，输入数值5； ⑥ 输入参数 "6400"
4. ⑦ 文本内容需要旋转90°，快捷键" ctrl " + 方向键 " ← "
5. ⑧ 文本填充需要取消勾选" 对象整体计算 "

标刻控制



建议参数调节：
速度(mm/s):500
功率(%):100
频率(KHZ):30

• 红光 (F1): 预览当前雕刻位置，红光矩形的预览模式

标刻(F2): 开始标刻

连续加工: 重复雕刻

选择加工: 多个对象, 选择其中一个雕刻

切换蓝红光

蓝光，各材质雕刻参数参考

图形、文字、矢量图			
材料	线间距	功率	速度
木材	0.03/ 0.01	100	500/700
竹子	0.005 / 0.001	100	500/700
塑料	0.03	100	1000 / 1500
皮革	0.03	100	1000 / 1500
石材	0.01	100	500
玻璃 陶瓷（需要配合色纸）	0.03	100	500
漆面材料	0.03/0.01	100	200/400

红光，各材质雕刻参数参考

图形、文字、矢量图			
材料	线间距	功率	速度
金属	0.01 / 0.005 / 0.001	100	300 / 500
漆面金属	0.005 / 0.001	100	500
塑料	0.03	100	1000 / 1500
皮革	0.05 / 0.01	100	1000 / 1500
石材	0.01	100	500
漆面玻璃	0.03	100	500
漆面材料	0.03	100	1000 / 1500

黑白图(普通位图)

材料	图片设置	功率	速度
金属		100	200
漆面金属	灰度 (勾选) 固定DPI (x300 y300)	100	300
塑料	网点 (勾选)	100	500
皮革	双向扫描 (勾选) 打点时间 (0.4~0.5ms)	100	500
石料	调整点功率 (勾选)	100	200
漆面材料		100	500

彩色图(风景、人物图像)

漆面金属	反转 (勾选) 灰度 (勾选)		
电镀金属	固定DPI (x500 y500)		
氧化金属	网点 (勾选) 双向扫描 (勾选) 打点时间 (0.4~0.5ms)	100	500
ABS塑料	调整点功率 (勾选)		

常见问题

I、机器通电无反应

1. 未通电：检查插座、开关、机身电源插座等，确保已插接到位且正常通电；检查面板上面的Power电源键，确保该键按下且健身灯光亮起。

II、无法连接电脑

1. USB线未连接：检查USB数据线电脑端和机器接口，确保插接到位，部分台式电脑前面板USB接口无效，需连接机身后方的插口。

2. 驱动未正常安装：按照操作指引完成驱动安装，安装完成后电脑将设备识别成串口则说明硬件连接OK。

3. 其他特殊情况：拔出USB数据线和电源，设备完全断电5S后，重新进行连接操作。

III、雕刻效果很浅或没有痕迹

1. 对焦不准：阅读使用手册对焦部分进行准确对焦。

2. 雕刻速度：过快，灼烧时间过短所致，阅读使用手册雕刻参数部分重新调整参数。

3. 图片过浅：导入的图片要清晰，线条过细，颜色过浅会直接影响雕刻效果。

4. 雕刻物摆放：被雕物体倾斜放置，激光的焦距是固定的，所以被雕物体要放平，与机身平行，反之则焦距不准，导致雕刻效果异常。

1.手机App下载

1、扫码以下二维码下载手机app



安卓
Android




苹果
IOS

系统要求: Android:7.0+, IOS:13.0+

注: 1、Android手机需要使用手机浏览器扫码二维码下载;
2、安装成功后需要给予相对于的权限;



MRCARVE



2. 手机app连接

- 1、插上手机连接接收器，插上机器电源，按下前面开机按键
- 2、手机打开WiFi搜索，连接上“ADD”密码：12345678
- 3、连接后手机会提示“当前WLAN不可上网，是否继续使用此WiFi？”请选择“使用”

查看APP界面是否连接成功：



已连接





未连接

连接上App后，请按照纸质参数表修改参数

步骤：App右下角“参数”→“振镜”下面指示位置

App右下角“参数”→“红光预览”下面指示位置



打标参数

标刻	红光预览	振镜	旋转轴
偏移X(mm): 0.000	偏移Y(mm): 0.000	角度(°): 0.000	
<input type="checkbox"/> XY互换	<input type="checkbox"/> X反向	<input type="checkbox"/> Y反向	区域尺寸(mm): 70
X方向: <input type="radio"/> 1.000	<input checked="" type="radio"/> 1.000	<input type="radio"/> 1.000	比例: 100.000 >>
Y方向: <input type="radio"/> 1.000	<input checked="" type="radio"/> 1.000	<input type="radio"/> 1.000	比例: 100.000 >>

关闭 确定

打标参数


标刻	红光预览	振镜	旋转轴
预览方式:	<input type="radio"/> 轮廓线	<input checked="" type="radio"/> 外接矩形	
红光速度(us):	3000		
偏移X(mm):	0.000	尺寸比例X:	1.000
偏移Y(mm):	0.000	尺寸比例Y:	1.000

关闭 确定





激光器需要选择“CO2”

3.软件各功能简介




- 1 菜单栏
- 2 绘图工具栏
- 3 标刻控制栏
- 4 内容显示框
- 5 辅助工具栏
- 6 对象属性栏

4. 绘制文字




- 1 点击左侧添加文本
 - 2 输入文字以及选择字体，点击“确定”文字编辑完成。
 - 3 工作区大小缩放
 - 4 工作区域，绘制内容请勿超出区域
 - 5 显示工作区域
 - 6 拖动工作区域
- W 宽度，单位: mm
- H 高度，单位: mm
- 锁定比例
- A+ 内容加大
- A- 内容减小
- 上下左右微调位置
中间是距离
单位: mm



属性, 图元属性
可二次编辑文字内容和字体

5. 文本填充



- 1 点击 填充，打开填充设置窗口
- 2 文字打标不需要设置其他参数，只需要修改“线间距”，默认参数为0.03

说明：

线间距是文字填充密度。数值越大，打标速度越快，雕刻颜色越浅；反之数值越小，则打标速度越慢，雕刻颜色越深；在原色金属、喷漆烤漆、氧化漆面、电镀金属、塑料、皮革、其它漆面材质上标刻，效果最佳。


6. 图片处理 (人物照片/彩色照片)

1 点击 ，选择自己所需的图片
图片

2 点击属性，在“图元属性”窗口里面勾选“灰度”、“网点”，“高级设置”里面“固定DPI”修改成500，打点时间修改成0.4


说明：
人物照片/彩色照片在喷漆烤漆面金属/氧化漆面电镀金属上雕刻，效果最佳。DPI数值越高，雕刻效果越清晰;打点时间越大，雕刻效果越深。

7. 图片处理 (普通位图)



1 点击 ，选择自己所需的图片
图片


2 点击属性，在“图元属性”窗口里面勾选“灰度”、“网点”，“高级设置”里面“固定DPI”修改成500，打点时间修改成0.4




说明：

人物照片/彩色照片在喷漆烤漆面金属/氧化漆面电镀金属上雕刻，效果最佳。DPI数值越高，雕刻效果越清晰;打点时间越大，雕刻效果越深。

8. 导入矢量文件雕刻



- 1 点击 选择所需的文件
图片
支持"PLT""DXF""AI"等格式
- 2 点击 打开"填充参数"窗口
填充
- 3 矢量文件填充，不需要设置其他参数，只需要修改"线间距"，
默认参数为0.03




说明：

人物照片/彩色照片在喷漆烤漆面金属/氧化漆面电镀金属上雕刻，效果最佳。DPI数值越高，雕刻效果越清晰;打点时间越大，雕刻效果越深。

关闭 确定

设置完成即可对焦和标刻，
步骤详见说明书“对焦”和“开始标刻”页面

9.RT5旋转轴-旋转文本标刻



① 第一步点击“设置”→“系统设置”里面修改标刻模式为“旋转轴标刻”；

② 打开参数→旋转轴，修改以下参数：

旋转轴方向: y;
勾选红光完成回到起始点；
按照实际打标物件填写工件直径；


③ 打开“运动轴测试”窗口，
选择“脉冲”后面填写一个数值，比如16625
点击左或者右箭头

观察滚轴是否带动物体（如杯子）转动一圈，
如果没有转动一圈，把“脉冲”的数值加大，如
果超过一圈，就减小，直到刚好转动一圈
转动一圈的“脉冲”值，即是“每转脉冲数”
最后，将测试好的脉冲值填写入“每转脉冲数”
即可。

说明：


工件直径不同，每转脉冲数不同，需要重
新按照以上方法修改每转脉冲数，视频教
程请联系客服索取。

10.RF2旋转轴-旋转文本标刻



① 第一步点击“设置”→“系统设置”里面修改标刻模式为“旋转轴标刻”；

② 打开参数→旋转轴，修改以下参数：
旋转轴方向：y;
勾选红光完成回到起始点；
每转脉冲数固定为：6400 （仅RF1旋转轴）
按照实际打标物件填写工件直径；




① 点击“文本”，输入雕刻内容

② 点击“填充”，将内容填充成实心（不填充雕刻出来只有轮廓线）


③ 点击“左旋”“右旋”，将文字如上图所示垂直。

11. 对焦与切换蓝/红光

M4-pro型号设备，可在此处切换“光纤模式”、“蓝光模式”
双光切换，适应更多雕刻材质。



1. 点击App右上角“对焦”，出现“正在对焦中....”此时，机器会出现两个红光点。
2. 放入测试卡片，轻按“Down”及“Up”按键调整，
两道红光汇聚成一个红点，完成对焦。
3. 激光头距离雕刻物的标准：
距离为120mm，以实测效果为准。



12. 开始标刻



打标参数

标刻	红光预览	振镜	旋转轴
开光延时(us): 300	关光延时(us): 100		
功率(%): 80	频率(khz): 30		
速度(mm/s): 300 <small>(图片网点模式打标无效)</small>	标刻方式:	选择加工 <input checked="" type="checkbox"/>	
标刻次数: 1	<input type="checkbox"/> 保存为默认值		

关闭 确定

- ① 绘制“文本”，“矢量图”，“图片”等内容后，点击右下角“参数”
- ② 在标刻栏目，输入功率、速度、填充线间距，可参考说明书“各材质雕刻参数参考”
- ③ 输入相对应的雕刻参数



信息提示

您确定红光预览？

关闭

预览

信息提示

您确定要标刻？

标刻次数 : 0

关闭

标刻

- ① 点击“预览”出现预览窗口，同时机器出现预览红光，摆放好雕刻的物体，即可标刻。

- ② 点击“标刻”即可完成打标。

MR.CARVE

本资料上所有内容均经过认真核对，如有任何印刷错漏或内容上的误解，可向本公司咨询。

注：产品若有技术改进，会增进新版手册中，恕不另行通知。产品外观，颜色如有改动，以实物为准。