

**BARRINGTON HIGH SCHOOL AUDITORIUM ADDITION  
PROJECT AREA TREE INVENTORY**

Tag No.	Location	Botanical Name	Common Name	Size	Condition	Form	Notes, Problems or Co-Leaders at Base	Sign./Key Tree
<b>EXISTING TREES - SHEET L2.2</b>								
436	SE property line	Juglans nigra	Black Walnut	34"	3	4		
437	SE property line	Juglans nigra	Black Walnut	24"	2	3		Key Tree
438	SE property	Picea pungens	Colorado Spruce	20"	5	5		
439	SE property	Picea pungens	Colorado Spruce	14"	6	NA		
440	SE property	Picea pungens	Colorado Spruce	12"	6	NA		
441	SE property	Acer negundo	Boxelder	14"	3	4	Growing into/through existing fence	
442	NE res. property	Acer platanoides	Norway Maple	22"	3	2	Some deadwood	
443	NE res. property	Thuja occidentalis	Arborvitae	18"	3	5	Limbed up; Co-leaders:4", 6", 8"	
444	N private prop	Juglans nigra	Black Walnut	13"	3	3	Private property, difficult to measure	
445	N private prop	Juglans nigra	Black Walnut	11"	3	3	Private property, difficult to measure	
446	N private prop	Ulmus americana	American Elm	11"	2	3	Private property, difficult to measure	
447	N private prop	Juglans nigra	Black Walnut	20"	2	3	Some dead wood	Sign. Tree
448	N private prop	Juglans nigra	Black Walnut	28"	3	3	Leaning to sunlight	
449	N private prop	Celtis occidentalis	Hackberry	10"	3	3	2 Co-leaders, 4" and 6"	
450	N private prop	Celtis occidentalis	Hackberry	6"	3	3	Little canopy	
451	N private prop	Celtis occidentalis	Hackberry	13"	2	3	Leaning somewhat	Sign. Tree
452	N private prop	Celtis occidentalis	Hackberry	7"	4	3	Growing into fence	
453	N private prop	Celtis occidentalis	Hackberry	6"	4	4	Growing into fence	
454	N private prop	Celtis occidentalis	Hackberry	23"	4	4	Growing into fence	
455	N private prop	Celtis occidentalis	Hackberry	11"	3	3	Somewhat lifted canopy for species	
456	N private prop	Celtis occidentalis	Hackberry	13"	2	3	Somewhat lifted canopy for species	Sign. Tree
457	South ROW	Celtis occidentalis	Common Hackberry	26"	3	3	Nipple gall	
458	South ROW	Celtis occidentalis	Common Hackberry	24"	2	2	Good form, high canopy with age	Sign. Tree
459	East ROW Hager	Pyrus calleryana	Callery Pear	14"	3	4	Growing into ComEd overhead lines	
460	East ROW Hager	Syringa reticulata	Japanese Tree Lilac	9"	3	3		
16	N private prop	Ulmus americana	American Elm	11"	3	4	Minor dead wood, 1 sided, 2 co-leaders, 5.5" each	
17	South property line	Quercus muehlenbergii	Chinquapin Oak	10"	2	3	Minor deadwood, weak crotch/multiple leaders	
18	South property line	Quercus muehlenbergii	Chinquapin Oak	14"	2	3		Sign. Tree
19	South property line	Quercus muehlenbergii	Chinquapin Oak	14"	2	3		Sign. Tree
23	South property line	Syringa x persica	Persian Lilac	18" (1' ht)	5	4	Dying, should be removed	
25	South property line	Gymnocladus dioicus	Kentucky Coffeetree	6"	2	3	Weak crotch, double leader	
26	South property line	Acer x freemanii	Freeman Maple	8"	2	3	Multiple leaders	
27	South property line	Acer x freemanii	Freeman Maple	7"	3	3	Minor dead wood, trunk scar also	
28	South property line	Gleditsia triacanthos	Honeylocust	7"	3	4	Some dead wood observed, leaning	
29	South property line	Gleditsia triacanthos	Honeylocust	7"	3	2	Some dead wood	
30	South property line	Acer rubrum	Red Maple	13"	2	3	Pruned for overhead wires	
31	South property line	Gymnocladus dioicus	Kentucky Coffeetree	8"	3	4	Double leader, pruned for overhead wires	
33	South property line	Acer freemanii	Freeman Maple	14"	3	4	Weak crotch, pruned canopy	
34	South property line	Acer freemanii	Freeman Maple	12"	3	4	Weak crotch, multiple leaders	
35	South property line	Acer freemanii	Freeman Maple	14"	3	4	Multiple leaders, pruned for overhead	
37	South property line	Tilia cordata	Littleleaf Linden	12"	3	3	Weak crotch, suckering, mult. lead.	

**BARRINGTON HIGH SCHOOL AUDITORIUM ADDITION  
PROJECT AREA TREE INVENTORY**

Tag No.	Location	Botanical Name	Common Name	Size	Condition	Form	Notes, Problems or Co-Leaders at Base	Sign./Key Tree
<b>EXISTING TREES - SHEET (L2.1)</b>								
40	South property line	Gleditsia triocanthos	Honeylocust	10"	3	4	Pruned for overhead wires, mult. Lead.	
47	South property line	Gleditsia triocanthos	Honeylocust	20"	3	3	Pruned for side wires, mult. leaders	
50	South property line	Gleditsia triocanthos	Honeylocust	14"	2	3	Weak crotch, multiple leaders	
51	South property line	Acer freemainii	Freeman Maple	20"	2	3	Weak crotch, poss. Girdling	
53	South property line	Acer freemainii	Freeman Maple	22"	3	3	Weak crotch, girdling roots, double leader	
55	South property line	Acer freemainii	Freeman Maple	18"	2	3	Weak crotch, multiple leaders	
57	South property line	Quercus imbricaria	Shingle Oak	14"	3	2	Minor deadwood	
58	South property line	Quercus imbricaria	Shingle Oak	16"	2	3	Minor dead wood, multiple leaders	
59	South property line	Quercus imbricaria	Shingle Oak	14"	2	3	Minor dead wood, multiple leaders	
60	South property line	Quercus imbricaria	Shingle Oak	12"	3	3	Minor dead wood	
61	South property line	Quercus imbricaria	Shingle Oak	14"	3	3	Minor dead wood	
62	South property line	Quercus imbricaria	Shingle Oak	12"	3	2	Minor dead wood, multiple leaders	
63	South property line	Quercus imbricaria	Shingle Oak	12"	3	3	Minor dead wood, multiple leaders	
95	S. wall of building	Picea pungens	Colorado Spruce	13"	4	5	Cytospora canker, top of tree dead	
96	S. wall of building	Picea pungens	Colorado Spruce	15"	4	5	Cytospora canker, top of tree dead	
97	S. wall of building	Acer saccharum	Sugar Maple	11"	3	3	Trunk scar, multiple leaders	
98	S. wall of building	Syringa reticulata	Japanese Tree Lilac	13" (1' ht)	4	3	Basal decay, basal scar	
99	S. wall of building	Syringa reticulata	Japanese Tree Lilac	9" (1' ht)	3	3		
100	S. wall of building	Syringa reticulata	Japanese Tree Lilac	14" (1' ht)	3	3	Minor dead wood, weak crotch	
101	S. wall of building	Malus sp.	Crabapple	17" (1' ht)	3	3	Minor dead wood, crown asymmetrical	
102	S. wall of building	Malus sp.	Crabapple	11" (1' ht)	3	4	Excessive lean, suckering	
105	S. wall of building	Amelanchier arborea	Downy Serviceberry	13" (1' ht)	3	3	Weak crotch	