



GOVT. OF ASSAM
TEZPUR FIRE & EMERGENCY SERVICES STATION,
DIST.-SONITPUR, ASSAM.

TEZPUR/F&ESS/61/

438

/2025

Dated : 24.06.2025.

Shri Sobhan Chowdhury
On behalf of **Adarsha Vidyalaya**
Proposed Assam type school building,
Located at Vill – Sologuri, Jamugurihat,
Dist.- Sonitpur, Assam.

Sub: Recommendation for Implementation of Fire Safety Measures in the proposed Assam type Educational building located at Vill – Sologuri, Jamugurihat, on the land under Dag No.565, Patta No.NIL, Mouza - Chilabandha, Dist.- Sonitpur, Assam.

Sir,

With Reference to the above you are requested to implement the additional Fire Safety Measures in the proposed Educational building located at the above noted location, for safety of lives and properties as well as the Buildings itself.

Recommendation of Fire Prevention and Fire safety measures as per N.B.C, 2016 , PART-4, Fire & Life Safety:-

1. Open Space as shown around building should be kept free from any obstruction for movement of fire & emergency services vehicle in case of any emergency.
 2. Passageways and Clearances:-
Width of the main entrance of the premises shall not be less than 4.5 mtrs. If an arch or covered gate is constructed, it shall have a clear head-room of not less than 5 mtrs.
 3. A Fire Point consisting of 3 (three) Nos. Fire bucket , 3 (three) Nos. of fire Beater , 1 (one) no. ceiling hook and dry sand should be made available in front of the building.
 4. Fire Extinguishers:
 - I. Adequate numbers of Co₂ or D.C.P extinguisher of 4.5/5Kg capacity with ISI mark Should be installed in each floor of the building. The extinguishers shall be distributed over the floor such that a person has to travel not more than 15 mtrs. to reach the nearest extinguisher or in each 100 sq.mtr. in floor area.
 - II. Adequate numbers of Co₂ Extinguisher of 4.5 kg capacity With ISI mark should be installed near the main Electric Panel board.
 - III. Adequate numbers of AFFF Extinguisher of 9 Ltrs capacity and Co₂ of 4.5 Kg capacity Extinguisher With ISI mark should be installed near generator room.
- N.B:-All extinguishers should be as per newly introduced Indian Standard –IS 15683:2006
5. To eliminate fire hazards, good housekeeping both outside and inside of the building shall be strictly maintained by the staff and management in the building.
 6. The staffs should be trained up how to operate the Fire fighting equipments as and when required.


.....contd. to the next page

Self Attested
Sobhan Chowdhury

7. A Fire fighting plan should be prepared. It should consists of Emergency Management teams. The members should be trained to operate the Fire fighting systems.
- 8.. Emergency Telephone Numbers should be displayed in and around the building.
9. Any alteration/modification and change of the building should be informed to the undersigned for taking necessary action.

PLEASE DO NOT TREAT THIS AS N.O.C, FORMAL N.O.C WILL BE ISSUED BY THE SPL. DGP CUM DIRECTOR OF FIRE & EMERGENCY SERVICES, ASSAM ONLY AFTER IMPLEMENTATION OF THE FIRE PREVENTIVE MEASURES AS SUGGESTED AND ON RECEIPT OF COMPLIANCE REPORT FROM YOUR END AND AFTER SUBMISSION OF SATISFACTORY INSPECTION REPORT BY TECHNICAL OFFICERS OF THIS DEPARTMENT.

Yours Faithfully,

 24/6/25


Senior Station Officer,
Tezpur Fire & ESS, Sonitpur, Assam.
Sr. Station Officer
Fire & Emergency Services Station
Tezpur, Sonitpur

Memo. No.TZP/F&ESS/61/ 438 (A) /2025

Dated : 24.06.2025.

Copy to:-

- ✓ 1. The SPL. DGP cum Director of Fire & Emergency Services, Assam, Guwahati for favour of kind information.

 24/6/25

Senior Station Officer,
Tezpur Fire & ESS, Sonitpur, Assam.

Sr. Station Officer
Fire & Emergency Services Station
Tezpur, Sonitpur

Self Attached
Sobham Choudhury.