

永磁单级螺杆空压机系列技术参数

Technical Parameter Table of Permanent magnet single stage screw air compressor series

机型 Model		WS-10A	WS-15A	WS-20A	WS-30A	WS-40A	WS-50A	WS-60A	WS-75A
参数 Parameters									
排气压力 (Mpa) Max Working Pressure		0.7	0.7	0.7	0.7	0.7	0.7	0.7	0.7
		0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8
		1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0
		1.2	1.2	1.2	1.2	1.2	1.2	1.2	1.2
容积流量 m³/min Volume flow		1.2	1.65	2.5	3.8	5.3	6.5	7.4	10.0
		1.1	1.5	2.3	3.6	5.0	6.2	7.0	9.6
		0.95	1.3	2.1	3.2	4.5	5.6	6.2	8.5
		0.8	1.1	1.9	2.7	4.0	5.0	5.6	7.6
功率 Power	KW	7.5	11	15	22	30	37	45	55
启动方式 Starting Mode		永磁变频	永磁变频	永磁变频	永磁变频	永磁变频	永磁变频	永磁变频	永磁变频
噪声Noise	Db(A)	68	70	70	75	75	76	76	78
出口尺寸 inch Air Outlet Pipe Diameter		RP3/4	RP1	RP3/4	RP1	RP1	RP1,1/2	RP1,1/2	RP2
重量Weight	kg	135	225	235	320	350	480	480	1010
外型尺寸 Dimension	长Length mm	750	1080	1000	1080	1120	1200	1250	1800
	宽 Width mm	610	750	780	880	880	980	1000	1250
	高 Height mm	850	1000	1020	1140	1200	1260	1390	1660