

# JAGAN METAL WORKS

(PREMIUM QUALITY ISI MARKED PIPE FITTINGS)

# VR

**“A product can be quickly outdated, but a successful brand is timeless”**

➡ **\*BEST FOR UNDERGROUND INSTALLATION** ➡ **RUST PROOF AND LEAK PROOF**



***“ FIT AND FORGE “***



PREMIUM QUALITY

VR

PIPE FITTING

HSN Code: 73079210  
M.R.P. in Rs. Per Pc.

PREMIUM QUALITY ISI FITTING

W.E.F 1st March 2022

Art No.  
**001**



**Elbow VR®**

12.50	21.00	32.00	50.00	70.00	104.00	198.00	267.00	480.00	2000.00
-------	-------	-------	-------	-------	--------	--------	--------	--------	---------

Art No.  
**002**



**Tee VR®**

<b>20.00</b>	32.00	44.00	65.00	88.00	135.00	252.00	361.00	591.00	2500.00
--------------	-------	-------	-------	-------	--------	--------	--------	--------	---------

Art No.  
**003**



**Socket VR®**

12.00	19.00	24.00	36.00	45.00	76.00	124.00	187.00	305.00	1550.00
-------	-------	-------	-------	-------	-------	--------	--------	--------	---------

Art No.  
**004**



**Union VR®**

37.00	50.00	70.00	105.00	127.00	195.00	365.00	507.00	715.00	2750.00
-------	-------	-------	--------	--------	--------	--------	--------	--------	---------

Art No.  
**005**



**Cross VR®**

32.00	46.00	75.00	125.00	165.00	250.00	390.00	520.00	1415.00	
-------	-------	-------	--------	--------	--------	--------	--------	---------	--

Art No.  
**006**



**3-Way VR®**

28.00	45.00	67.00	105.00	145.00	225.00	330.00	445.00	905.00	
-------	-------	-------	--------	--------	--------	--------	--------	--------	--

Art No.  
**007**



**Nipple VR®**

14.00	25.00	30.00	50.00	65.00	95.00	175.00	265.00	485.00	2050.00
-------	-------	-------	-------	-------	-------	--------	--------	--------	---------

## PLEASE NOTE:-

- \*Reducing Elbows, Tees & Sockets upto 6" are available. The rates of the bigger size will be charged for them.
- \*Elbows, Tees, Sockets 8 mm & 10 mm are also available. The rates of 15 mm will be charged for them.
- \*The user must check the lines with the help of pressure pump before plastering or flooring.
- \*G.I. Pipe lines in floors are required to be well concreted.