



AUDI Q2: BA6195			
Vinnnumber:	WAUZZZGA1LA079383	Versionname:	1.6 30 TDI 85kW
First Registrationdate:	22/09/2020	Fiscalpower:	
Expertise Mileage:	103554	Power Kw:	85
Bodytype:		Body colour:	Dark Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1707
Fueltype:	Diesel		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options			
Number of keys total:	2	Sun Roof electric:	
Cruise Control:		Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Seats F heated:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

215/50/18/92 V				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				6.0
Tyre profile depth RL:				7.0
Tyre profile depth RR:				7.0
Tyre size FL:				215/50 R 18 92 V
Tyre type FL:				All season
Tyre make FL:				2480
Tyre make RL:				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT 1371,31

Door panel FL, Scratch(es), Acceptable 0,00



Bonnet, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable

0,00



Wing RL, Scratch(es), Acceptable

0,00



Roof pillar L, Scratch(es), Acceptable

0,00



Alloy rim FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Boot carpet, Stain, Cleaning

28,43



Tailgate / Boot, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Bumper trim R, Scratch(es), Smart repair

113,74



Wheel aperture RR, Dent(s) and scratch(es), Acceptable

0,00



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)

300,51



Wing trim FR, Scratch(es), Repair and paint (complete)

157,71



Outside rear-view mirror cover R (upper), Scratch(es), Smart repair

113,74



Door FR, Dent(s) and scratch(es), Acceptable

0,00



Roof, Scratch(es), Repair and paint (complete)

657,18

