

सहायक अभियंता का कार्यालय
उप मंडल.नं.- ८
निर्माण मंडल अ.लो.नि.वि.
डिग्लीपूर उ. एवं म. अन्धमान



OFFICE OF THE ASSISTANT ENGINEER
SUB DIVISION NO-II
CONSTRUCTION DIVISION, A.P.W.D.
DIGLIPUR, N & M ANDAMANS

No.2-9/SD-II/CD/DP/2023/ 805

Diglipur, dated the 03 December 2024

STABILITY CERTIFICATE

It is to certify that the school building of "**BHARATIYA VIDYA BHAVAN MONDAL PUBLIC SCHOOL**" under Diglipur Tehsil was inspected by APWD team and observed that the buildings (01 No.double storied RCC framed structure & 03 Nos. single storied RCC framed structure)are structurally stable for running school in normal condition.

सहायक अभियंता/Assistant Engineer
उप मंडल.नं.- II/ Sub Division No-II
निर्माण मंडल, अ.लो.नि.वि.ए डिग्लीपूर/CD,APWD, Diglipur

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- | | |
|---|--|
| 1. Name of the Officer | MANU THOMAS |
| 2. Name of the School | BHARATIYA VIDYA BHAVAN,
MONDAL PUBLIC SCHOOL, |
| 3. Location with name of Education District/ Sub. District | MADHUPUR, NORTH & MIDDLE ANDAMAN |
| 4. Classification of Building as specified in column 4 of the application for fitness certificate and size. | 1. RCC framed structure single storied
(05 Class Room)-Block-A
2. RCC framed structure single storied
(05 Class Room)-Block-B
3. RCC framed structure double storied
(06 Class Room)-Block-D
4. RCC framed structure single storied
(05 Class Room)-Block-C |
| 5. Period for which the certificate is issued | |
| 6. Nature of defects , if any | Not Applicable |
| a) Foundation and basement | |
| b) Superstructure | 3 Nos. Single Storied & 01 No. Double Storied |
| c) Doors and Windows | Good condition. |
| d) Wood work wrought and put up | Not Applicable |
| e) Roof | Good |
| f) Flooring | No defect found |
| g) Miscellaneous (Cracks, etc.) | Not Visible. |
| 7. Any major defects noticed which will render the building unsafe in any manner . | No such defects noticed |
| 8. Whether maintenance works have been done properly | Not Applicable |
| 9. Whether the structure is sound or not for conducting classes | Sound |


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 21.11.2024 and found to be fit to conduct classes, for the period 2024-25 for the reasons stated above.

Place : Diglipur

Date : 03.12.2024


 सहायक अभियंता/Assistant Engineer
 उप मंडल.नं.- II/ Sub Division No-II
 निर्माण मंडल, अ.लो.नि.वि.ए डिग्लीपूर/CD,APWD, Diglipur